HGREG.com INSPECTION REPORT

	Complian	Repaired		C	Compliant	Repaire
Tie rod	•	0	Gusset	L R		0
Coupling rod	•	\circ	Steering damper			0
Idler arm	•		Steering system			0
Steering column	•	0	Fastening device			0
Hoses/Fittings	•	0	Slip joint			0
Steering rack	•	0	Control lever			0
External nozzle	L R	0	Steering lever			0
Interior nozzle	L R	0	Track arm			0
Power steering pump	•	0	Power steering			0
Interior ball joint	L R	0	Steering wheel			0
Exterior ball joint	L R	0	Adjustable steering wheel		•	0
Alignment	•	0	Universal joint		•	0

En	gine Ex	khaus	t Transmission		
	Compliant	Repaired		Compliant	Repaired
Traction control light	•		Clutch	•	0
Check engine light	•	0	Master cylinder	•	0
Engine oil leak and transmission	•		4X4 verification	•	0
Engine performance (road test)	•	0	Fastener	•	0
Fuel tank	•		Gauge	•	
Hose	•	0	Drive shaft protector	•	0
Fuel tank cap	•		Catalyst	•	0
Exhaust system	•	\circ	Resonator	•	0
Engine mounts	•		Muffler	•	0
Transmission mounts	•	0	Safety structure	•	0
Transmission performance	•	0	Exhaust pipe	•	0

	Ele	ctrica	ıl system		
	Compliant	Repaired		Compliant	Repaired
Charging station	•		Cable	•	
Alternator	•	0	Battery box cover	•	\circ
Battery	•				

	N	laint	enance		
	Compliant	Repaired		Compliant	Repaired
Engine oil	•		Fluid level	•	0
Oil filter	•	0			

		Saf	ety		
	Compliar	t Repaired		Compliant	Repaired
Safety belts (front seats)	L R	0	Front windshield wiper	•	
Safety belts (rear seats)	L R	0	Rear windshield wiper	•	0
Airbag indicator (warning light)	•	0	Front windshield washer system	•	
Front seat adjustment mechanism	L R	0	Rear windshield washer system	•	0
Rear seat adjustement mechanism	L R	0	Headrest	•	
Hood latch	•	0	Benches and seats	•	0
Trunk latch	•	0	Hinge	•	
Door lock	•	0	Mudguards	•	0
Air conditionning system	•	0	Washer fluid (min, max)	•	
Heating system	•	0			

Accessories								
		Compliant	Repaired		Compliant	Repaired		
Front speakers	L R	•	0	Interior ceiling light	•			
Rear speakers	L R	•	0	Sunroof	•	\circ		
Radio			0	Defrost	•			
Glove compartment and other	er storage space		0	Heating system	•	\circ		
Socket (12V)			0	Interior sunvisor	•			
Car door remote control			0					
			1					

	Comp	liant Repaired			Compliant	Repaire
Taillights	L C R		Daytime running lights	L R		
Hazard warning lights	F R L R		Fog lights	L R		\circ
Turn signal lights	F R L R		Dashboard lights			
License plate lights		0	Switch		•	\circ
Reverse lights	L R		Reflector		•	
Position lights	L R	0	Indicator lamps		•	
Horn			Headlight cover		•	
Headlights	L R	0				
		'				

		Compliant	Repaired		Compliant	Repaired
Wheel bearings	FL FR RL RR	•		Valves/TPMS valves	•	
Jack and rescue tools		•	0	Bolts, studs and nuts	•	0
Front left tire	/32	•		Rim	•	
Front right tire	/32	•	0	Spindle wheels radius	•	0
Rear left tire	/32	•		Wheel	•	
Rear right tire	/32	•	0	Wheel spacers	•	0
			Bra	•		

	Compliant	Repaired		Compliant	Repaired
Hoses	•	0	Brake pedal travel	•	
Wheel cylinders	•	\circ	ABS system	•	0
Front dic	mm		Parking brake	•	
Rear disc	mm	\circ	Fastening element	•	0
Front brake linning	mm		Brake fluid (level)	•	
Rear brake linning	mm		Fuel tank	•	
Drum brake	•		Brake pedal	•	
Brake caliper	F R	0	Brake coupling	•	0
Master cylinder	•	0			

		Wind	ows a	nd mirrors			
		Compliant	Repaired			Compliant	Repaired
Windshield	F R	•		Exterior rear-view mirror	L R	•	
Window regulator	FL FR RL RR	•	0	Interior rear-view mirror		•	0
Rear window		•		Side windows	F R	•	
Defroster		•	0				

•		Side windows	F R	0
•	0			
Sus	pensio	on system		
		•		
Compliant	Repaired		Compliant	Repaired
•	0	Air suspension	•	0
L R	0	Stirrup blades	•	0
L R	0	Anchor	•	0
•	0	Air canalisation	•	0
		Rubber pad		0
	Compliant L R L R	Suspension Compliant Repaired L R	Suspension system Compliant Repaired Air suspension L R	Suspension system Compliant Repaired Compliant Air suspension L R

Lower suspension arm

Upper suspension arm

Shackles

Springs

Master blade

Coupling

Level valve

Leaf spring support